


Gather Ingredients



2 Add Nicotine Shot



\* If the bottle nib has an O-ring attached, remove it prior to step 3.

Failure to do this will result in leakage.

Shake Thoroughly



Q-"Why is the nicotine so harsh?"

**A** - "You need to allow the mix to breathe. The best way to do this is by taking the lid off and leaving it in a cool dark place 3-7 days."

For more info google:

"e liquid steeping methods"



To Acheive 3mg

- 60ml Shortfill (50ml 0mg): 1x18mg Nic shot
- 100ml Shortfill (80ml 0mg): 2x15mg Nic shots
- 120ml Shortfill (100ml 0mg): 2x18mg Nic shots